



## Legal and technical information pertaining to radio emitting devices

**COUNTRY:** INDONESIA

**LABEL NAME:** SDPPI



### Special Instructions for marking placement:

The Certificate bearer shall make and attach the label on each instrument and set of equipment and on the packaging before it is sold in Indonesia.

Certificate holder must attach warning sign on their Telecommunication tools and/or devices except for short range devices.

The packaging label must contain the QR code that can be found on the bottom right of each certificate.

If the labeling is not possible to be attached to the device then it is possible for the applicant to print the label in the user manual or installation instructions.

It is recommended that this document is kept alongside or inside the owner's manual

This document is available at the following web address:

<https://www.volkswagen.com/generalinfo>

Volkswagen hereby informs you of Volkswagen AG's declaration that the following components conform to the technical requirements as set out by SDPPI SRD.



Dilarang melakukan perubahan spesifikasi yang dapat menimbulkan gangguan fisik dan/atau elektromagnetik terhadap lingkungan sekitarnya

Dilarang melakukan perubahan spesifikasi yang dapat menimbulkan gangguan fisik dan/ atau elektromagnetik terhadap lingkungan sekitarnya

Volkswagen AG, Berliner Ring 2,  
38440 Wolfsburg, Deutschland  
11/2023 Volkswagen AG



- Radio service




- Models



- Requirements for SRD



Combi	Taigun Tiguan/Allspace	<div data-bbox="309 263 392 343"></div> <div data-bbox="414 263 627 343">Nomor Sertifikat 86721/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 263 743 343"></div> <div data-bbox="766 263 978 343">Nomor Sertifikat 85366/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="309 359 392 438"></div> <div data-bbox="414 359 627 438">Nomor Sertifikat 85688/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 359 743 438"></div> <div data-bbox="766 359 978 438">Nomor Sertifikat 86619/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="309 454 392 534"></div> <div data-bbox="414 454 627 534">Nomor Sertifikat 86719/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 454 743 534"></div> <div data-bbox="766 454 978 534">Nomor Sertifikat 85359/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="309 550 392 630"></div> <div data-bbox="414 550 627 630">Nomor Sertifikat 83130/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 550 743 630"></div> <div data-bbox="766 550 978 630">Nomor Sertifikat 86620/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="309 646 392 726"></div> <div data-bbox="414 646 627 726">Nomor Sertifikat 85691/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 646 743 726"></div> <div data-bbox="766 646 978 726">Nomor Sertifikat 88082/SDPPI/2023 PLG ID: 4334</div> <div data-bbox="309 742 392 821"></div> <div data-bbox="414 742 627 821">Nomor Sertifikat 97530/SDPPI/2024 PLG ID: 4334</div> <div data-bbox="660 742 743 821"></div> <div data-bbox="766 742 978 821">Nomor Sertifikat 88081/SDPPI/2023 PLG ID: 4334</div> <div data-bbox="309 837 392 917"></div> <div data-bbox="414 837 627 917">Nomor Sertifikat 85737/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 837 743 917"></div> <div data-bbox="766 837 978 917">Nomor Sertifikat 88077/SDPPI/2023 PLG ID: 4334</div> <div data-bbox="309 933 392 1013"></div> <div data-bbox="414 933 627 1013">Nomor Sertifikat 85678/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 933 743 1013"></div> <div data-bbox="766 933 978 1013">Nomor Sertifikat 89912/SDPPI/2023 PLG ID: 4334</div> <div data-bbox="309 1029 392 1109"></div> <div data-bbox="414 1029 627 1109">Nomor Sertifikat 85345/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 1029 743 1109"></div> <div data-bbox="766 1029 978 1109">Nomor Sertifikat 83130/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="309 1125 392 1204"></div> <div data-bbox="414 1125 627 1204">Nomor Sertifikat 85693/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="660 1125 743 1204"></div> <div data-bbox="766 1125 978 1204">Nomor Sertifikat 83196/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="309 1220 392 1300"></div> <div data-bbox="414 1220 627 1300">Nomor Sertifikat 86618/SDPPI/2022 PLG ID: 4334</div>	Remote Key	Taigun Tiguan/Allspace	<div data-bbox="1258 263 1344 343"></div> <div data-bbox="1366 263 1579 343">Nomor Sertifikat 82866/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="1612 263 1695 343"></div> <div data-bbox="1718 263 1930 343">Nomor Sertifikat 88449/SDPPI/202 PLG ID: 4334</div> <div data-bbox="1258 359 1344 438"></div> <div data-bbox="1366 359 1579 438">Nomor Sertifikat 98463/SDPPI/2024 PLG ID: 4334</div> <div data-bbox="1612 359 1695 438"></div> <div data-bbox="1718 359 1930 438">Nomor Sertifikat 103398/SDPPI/2024 PLG ID: 4334</div> <div data-bbox="1258 454 1344 534"></div> <div data-bbox="1366 454 1579 534">Nomor Sertifikat 85384/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="1612 454 1695 534"></div> <div data-bbox="1718 454 1930 534">Nomor Sertifikat 107470/DJID/2025 PLG ID: 4334</div> <div data-bbox="1258 550 1344 630"></div> <div data-bbox="1366 550 1579 630">Nomor Sertifikat 98493/SDPPI/2024 PLG ID: 4334</div>
			Central control unit	Taigun Tiguan/Allspace	<div data-bbox="1258 678 1344 758"></div> <div data-bbox="1366 678 1579 758">Nomor Sertifikat 82568/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="1612 678 1695 758"></div> <div data-bbox="1718 678 1930 758">Nomor Sertifikat 77920/SDPPI/2021 PLG ID: 4334</div> <div data-bbox="1258 774 1344 853"></div> <div data-bbox="1366 774 1579 853">Nomor Sertifikat 104230/SDPPI/2024 PLG ID: 4334</div>
				Taigun Tiguan/Allspace	<div data-bbox="1258 885 1344 965"></div> <div data-bbox="1366 885 1579 965">Nomor Sertifikat 93905/SDPPI/2023 PLG ID: 4334</div> <div data-bbox="1612 885 1695 965"></div> <div data-bbox="1718 885 1930 965">Nomor Sertifikat 99623/SDPPI/2024 PLG ID: 4334</div>
			Radare	Taigun Tiguan/Allspace	<div data-bbox="1258 1013 1344 1093"></div> <div data-bbox="1366 1013 1579 1093">Nomor Sertifikat 97858/SDPPI/2024 PLG ID: 4334</div> <div data-bbox="1612 1013 1695 1093"></div> <div data-bbox="1718 1013 1930 1093">Nomor Sertifikat 101210/SDPPI/2024 PLG ID: 4334</div> <div data-bbox="1258 1109 1344 1189"></div> <div data-bbox="1366 1109 1579 1189">Nomor Sertifikat 10254/SDPPI/2024 PLG ID: 4334</div> <div data-bbox="1612 1109 1695 1189"></div> <div data-bbox="1718 1109 1930 1189">Nomor Sertifikat 97856/SDPPI/2024 PLG ID: 4334</div>
			RDK	Taigun Tiguan/Allspace	<div data-bbox="1258 1220 1344 1300"></div> <div data-bbox="1366 1220 1579 1300">Nomor Sertifikat 86720/SDPPI/2022 PLG ID: 4334</div> <div data-bbox="1612 1220 1695 1300"></div> <div data-bbox="1718 1220 1930 1300">Nomor Sertifikat 83645/SDPPI/2022 PLG ID: 4334</div>

  
 Dilarang melakukan perubahan  
 Spesifikasi yang dapat  
 Menimbulkan gangguan fisik  
 dan/atau elektromagnetik  
 terhadap lingkungan sekitarnya